

GENWAL COAL COMPANY

December 1, 1993

RECEIVED

DEC 02 1993

DIVISION OF
OIL, GAS & MINING

Mr. Daron Haddock
Division of Oil, Gas & Mining
3 Triad Center, Suite 350
355 West North Temple
Salt Lake City, UT 84180-1203

RE: Permit #ACT 015-032
DOGM Letter dated November 12, 1993 (ACT/015/032-93G Folder 3)
Memo to File from Sharon Falvey dated November 10, 1993

Dear Mr. Haddock:

A submittal was sent to you dated October 12, 1993 concerning the abatement of NOV 93-43-1-1. Also included in the same submittal was hydrologic calculations for other changes in the operations area of the Crandall Canyon Mine. These changes were to become part of Appendix 7-7 and 7-11. Also Included was a revised Plate 7-5A, revision date 10/12/93 which was to replace the Approved Plate 7-5A, revision date 5/4/93.

The NOV 93-43-1-1 was terminated but the other changes were disapproved. The amendment was considered incomplete based mostly on a Plate 7-5A, revision 12/9/91. The amendment should have been compared to the latest approved Plate 7-5A, revision 5/4/93.

There was a question on which revision of Plate 7-5A was the last to be approved. In turn I called the USFS to see what package was received by them. Mr. Carter Reed verified the Plate 7-5A, revision 5/4/93, was sent to them with a cover letter from DOGM, dated July 30, 1993, showing it to be the approved plate. I then checked with the Price office of DOGM and they also have the latest revision and package submitted by Genwal on May 13, 1993.

This brings further concern to Genwal that there may be more within our Mine and Reclamation Plan at DOGM that may not have been updated from the approved submittal of May 13, 1993. Please check your copy of our MRP and update those documents that need to be with the approved information from the May 13, 1993 submittal.

At this time Genwal requests that DOGM again review the latest submittal for amendment dated October 12, 1993 in conjunction with the latest approved Plate 7-5A.

Should you have any questions or need additional information, please contact me at 687-9813.

Sincerely,
GENWAL COAL COMPANY

A handwritten signature in cursive script, appearing to read "Larry W. Johnson".

Larry W. Johnson
Engineer

A handwritten signature in cursive script, appearing to read "R. Jay Marshall".

R. Jay Marshall
Chief Engineer